


SiPM status report

05.03.2017.

Balazs Ujvari

Still some mechanics works

- The SiPMs and preamps will be out of the original box



the main amplifier is inside
cables (signal and optical)
on the top we need a light tight box

I bought three boxes none of good
enough
ordered a new one

- Tomorrow we connect the top and the box put somewhere and start the DAQ